

US EPA RECORDS CENTER REGION 5

Industrial Park • Hibbing, Minn. 55746 U.S.A. • Phone: 218/262-5211 Telex: 29-4446

RECEIVED

June 5, 1981

MINN POLLUTION CONTROL AGENCY

Mr. Mike Somers
Minnesota Pollution Control Agency
1935 W. County Road B2
Roseville, Mn 55113

Dear Mike:

Due to changes in managerial practices, financial responsibilities and EPA regulations, Irathane Systems has made several changes in its disposal procedures for hazardous wastes. Enclosed are two tables which address these changes. Table #1 lists individually each waste stream and all applicable changes in disposal. Table #2 lists the changes in non-hazardous waste quantities from the table in the letter of Ken Podpeskar of March'12, 1981.

As was requested by Ken Podpeskar (June 4, 1981) the following description was written to advise MPCA of Irathane's efforts to "clean up the backyard" at each the north and south buildings.

- (1) 10,000 gallons of waste solvent have been segregated, sampled and are set for incineration in Chicago, Illinois.
- (2) 48 drums of solid non-hazardous resins have been segregated, checked and are planned for disposal at the Hibbing landfill.
- (3) 17 drums of liquid non-hazardous materials have been segragated, checked and will potentially be disposed of at the Hibbing Waste Disposal Plant.
- (4) Approximately 2375 gallons of polyurethane components have been individually mixed and reacted to form solid polyurethanes. This material is non-hazardous and intended for disposal at the Hibbing landfill.
- (5) Approximately 300 drums of solid polyurethane resulting from equipment flush have been checked, segregated and are intended for disposal at the Hibbing landfill. These drums now stored in the south yard, were previously stored at the north plant, and were not included in the table of March 12.

Due to modifications in equipment, the amount of solvent used during equipment flush has been reduced, causing the resulting material to cure and solidify, thus rendering it non-hazardous. An amended notification on this waste stream is enclosed.

RUBBER PRODUCTS DIVISION

Mike Somers
Minnesota Pollution Control Agency
June 5, 1981 -2-

- (6) Approximately 300 drums of Irathane prepolymers have been checked and segregated as to the physical state before and after heating. Approximately 150 of these drums have been moisture cured, thus will not liquidify at temperatures up to 200°F, and as such are considered as non-hazardous wastes to be disposed of at the Hibbing landfill. The remaining 150 drums will be incinerated in Chicago due to liquidification at temperatures of 200°F. or below.
- (7) Approximately 40 2,5 gallon pails of 4,4' methylene-bis-2-chloroaniline have been crushed and placed in 7- (17-H type) D.O.T. approved drums as was suggested by U.S. Ecology. These pails either had residual present or were less than half full of this material. This procedure has been in effect since empty pails whose previous contents were MOCA are considered hazardous. You have asked that this procedure be halted until MPCA has okayed it. If the procedure is not okay, MPCA has the responsibility to provide Irathane with an alternate acceptable procedure.
- (8) Approximately 1500 miscellaneous drums are intended for reclaimation or disposal as scrap metal. The following companies will accept these drums:

Worum Chemical

Solvent drums

Reclaimation

Some Resin drums

Consolidated

TDI/MDI Drums
White prepolymer drums

Nashban

Drums in good condition
Drums in bad condition
Scrap waste

Irathane Systems has been working on the above cleanup activities full time since March 1981. We are making every effort to stay in compliance with MPCA/EPA regulations while keeping MPCA informed of Irathane's hazardous waste activities. Although we are attempting to clean up both back yards prior to June 20, 1981, it is likely that this deadline will not be met due to the delay of our company disposal request, the halting of all cleanup activities dealing with MOCA in addition to new regulations by EPA. With this in mind, Irathane will now adhere to July 20, 1981 as the extension date for compliance with MPCA regulations for facilities storage of hazardous wastes.

Sincerely,

IRATHANE SYSTEMS INGORPORATED

/ どんたん し Laurie Potter

Environmental Consultant

LP:nb Enclosures

			i i	
1#0 335	1 N C I N ER H 7 1 0 N	16000160 JL	645018000 CI -71 53454177 0111717438	81-0
0	24181B	0000100 EF LAN	10001	t1-0
0	JONING TENLA	3NN 41 HA 1 2143 T 2120	WORLING EITEM	91-0
0	7312128	14 I BABING A ANDI=1CL	2NAHTAM1	91-0
(17 mi-0)	NMONYNH	NAJUSTEHW DINIELENH	31441441	141-19
FCF 335°	7612179	111881N6 LANDI-16L	514.37 2/22	E1- q
	NOTHE 12HAT ENDIN	7 14 14 14 1	2437242 -1 RHTHANS.	
0	D21 R.1 AL	0000100EE TVN	TRATHANE	21-4
NNNN	74131170	6000003 50	· MESHO MUSOU	11-0
SWNZOOI	DURIRE	0000100EE LAN	MORUM CHEM	01-0
N3LUM O	NOILWINIDA	NASH BAN 2010	NHO HISUN	6-0
100E		HIBOND SMODIH	3NHH2HX1	* 8-0
15TA 335	NO17A512451 T123 N	3N & H L & Y 1	2/27/2/120 2/12/2/120	t-o
187	NOITH 21361 21 113 (1	3NH+17 PAS 1	-3NHH1HAI	9-0
477#	かれられた	TI1-10NHY 2N1 (7814)	3N71FH71	S-0°
h=#	1017 FL 12 12 L	3NAH17AX1 B	51V3L5F5 3NUHLUUI	h - P
1#0	NO17 4513 M19 W1	DNINALLANDINA DNINALANDINA DNINALANDI	5765 4M 010017 435	E-9
338 1#0 338	NOILBABNIDINI	180001E0 (71)	645018000 (1.71) 53484M 011117 435	7-0
16/21/1-07 16/20/01	NOITHABULDINI	150001E0 (71)	57254M 010017 135	. /-0
00000000000000000000000000000000000000	00H12 3 W	2350081TP	TRAINSPORTER	H P.

		:	j	
, MAN	TRANSPORTER	D15 125 5K	METHOD	CURRENT QUANTITY
0 #	186 NO	PERRIT NO	748.77962	STORED
D-19	SET LIGHTIO WASTES 12-10000810549	ALBUINN INC (12) 03100031	INCINER'ATION	FULL DRU
D-20	SET LIVEIN WAS TES IL-DUONIOS49	ALBURNINC (11) 03160031	, NCINEKATION	SEE # 22 EMPTY UK
1 D-21	IRATHANE SYSTEMS	HIBSTAGE KANDFILL	CINN NOUN (CIG 100 COLAICIA C CORNOS	SEE TE COAM
D-22	NASHBAN BAKKEL EL CTK; WOKUM CHEEL	MARKEL & CTRY WONGEN CHERL	L'ECLAININTIUN	1500 EMPTY DRUMS; (L) 14.14, 20, 21, 2
0-23	TROOM	NV7 30010000	BURIAL	150 DRUM
VD-24	112H THANE SUISTEALS	14 1 m B ING XAIRDI = 10C	RECITRACIZATION	3275 gre (5040) 542
D-25	IRATHANE SUNTERIS	1 R.H THANE H 1BBING XHINDPILL 1 RHTHINE	BUKIAL NEUT PHUIZATION	#24 SEE
D-26	SUSTEMS	1411351116 LANDIELE	EURIAL.	#24
		· · · · · · · · · · · · · · · · · · ·		
* Des clo.	incin #8			
i Ffre-	Springer Change	Loant		

Table #2

Generation of Non-Hazard Waste at ISI

ltem No.	MN D-No.	Description	Quantity Prescnt @ Company	*Weekly Production
1,	9	TDI & TDI based prepolymer empty drums	20 empty drums	1
2,	9	MD1 & MD1 based prepolymer empty drums	20 empty drums	20 drums
,3,	12	Rubber scraps - cured/uncured	0	200#
Ж	-	Office & lunchroom wastes	0	100 cu ft
5.	. 14	1,4BD wastes 1,4BD empty drums	17 full drums. See D#22 for empty drums	No wastes 2 drums
6.		Ethylene Glycol waste Ethylene empty drums	O full drums O empty drums	1 drum
7.	22	Solvent drums empty	1500 empty drums (D#14,19,20,21,22)	6-10/wk
. 8.	15	Floor sweepings	2	See No. 10
. 9,	-	Lab solid wastes	0	45 cu ft
.10.	24	Solid urethane pieces, pails, drums	150 drums 2375 gal. (solid)	72 cu ft
,11,	21	Polyether resin Polyether empty drums	48 full (solid) drums. See D#14 fo	No waste r25 drums
,12,	21	Polyester resin Polyester empty drums	liquid drums. See D#22 for empty drums.	No waste 5-10 drums
13,	_	Fiberboard boxes	0	See No. 10
14.	-	Empty silicon dioxide bags	0	12-18
15.	-	Empty pails of rubber adhesive	30 5 gallon pails	1 - 5 gal pail
16.	8	Equipment flush, solid urethan	e 300 drums	1 drum

<sup>\*</sup> Quantities on hand and produced weekly are strictly estimates.